




Alaska User Manual

Intel LGA775,1156(i3,i5,i7)/Intel LGA1366(i7)/AMD AM2,AM2+ and AM3

Inspiring Cooling Technology
www.GlacialTech.com

List of Parts




- A** IceTherm II thermal grease
- B** Fan holders
- C** Heatpipe Module
- D** 12 cm axial fan
- E** Spring-screw for Intel
- F** Screws for AMD
- G** M3 screws for the clips
- H** Screw driver
- I** LGA775/1156/1366 Clips
- J** AMD Clips
- K** LGA1156 backplate
- L** LGA775 backplate
- M** LGA1366 backplate

Installation Step

Step 1


Fix the fan holders over the cooler.




Step 3

Use M3 screws to fix up all the clips of Intel and AMD.

For Intel




For AMD



Step 2



Smeared thermal grease around the copper base.




Step 4

Put the 4 fasteners into the 4 holes of the motherboard.



For Intel



For AMD



A for AMD Socket AM2
B for AMD Socket 754,939,940,F
C for Intel LGA775





Step 5

Fix the Fan on the cooler within fan holders.



Step 6

Connect the fan cable connector to the motherboard CPU fan header.



Breathing Effect

- FAN APPROVED BY CE & TUV & UL
- The specifications are subject to change without notice. All brand names and trademarks are the properties of their respective owners.

GlacialTech[®]
Enlighten Your Humanity

For further information, please consult our website: www.GlacialTech.com
© 2010 GlacialTech Inc. All rights reserved.

17-ALASS000001