



Inspiring Cooling Technology
www.GlacialTech.com



User Manual

Siberia

Intel LGA775,1156 (i3, i5, i7) and LGA1366(i7)
AMD AM2, AM2+ and AM3

List of Parts


- A** Heatpipe Module
- B** LGA775 backplate
- C** LGA1366 backplate
- D** LGA1156 backplate
- E** LGA775/1156/1366 Clips
- F** AMD Clips
- G** Spring-screw for Intel
- H** Screws for AMD
- I** M3 screws for all clips
- J** Screw driver
- K** IceTherm II thermal grease



Installation Step

Step.1


Print thermal grease on the copper base.




Step.2

Use M3 screws to fix all Intel and AMD clips.

For Intel



For AMD



Step.3

Please the 4 fasteners at the 4 holes of motherboard.


For Intel




1. Tear off the sticker from the backplate.



2. Put the 4 backplate holes onto the 4 motherboard holes.



For AMD



According to motherboard industry designing guidelines, it is required to include a rear plate as standard packaging, therefore the Alaska will not include the rear panel plate in the packaging.


A for AMD Socket AM2
B for AMD Socket 754,939,940,F
C for Intel LGA775



The bigger screw is for AMD, the small one is for Intel.




Put the black ring inside the screw to fix screw and backplate.



Step.4

Connect the fan cable connector to the motherboard CPU fan header.



GlacialTech®

Enlighten Your Humanity

- FAN APPROVED BY CE & UL
- The specifications are subject to change without notice. All brand names and trademarks are the properties of their respective owners.

For further information, please consult our website: www.GlacialTech.com
© 2010 GlacialTech Inc. All rights reserved.

17-SIBES000001