

# User Manual




Inspiring Cooling Technology  
[www.GlacialTech.com](http://www.GlacialTech.com)

## • Installation




### Step 1

Remove the plastic cover.



### Step 2

Place the fasteners at the motherboard's holes.




### Step 3

Make sure that all the fasteners are at the original status.




( Error! )




### Step 4

Push down on the top of fasteners, you should hear a "click" when pushing down the fastener.



( Error! )

Do not put hands on the top of fan as the pressing point by installation in order to avoid fan hub damage.



### Step 5

Connect the fan cable connector to the motherboard CPU fan header.

- FAN APPROVED BY CE
- The specifications are subject to change without notice. All brand names and trademarks are the properties of their respective owners.

For further information, please consult our website: [www.GlacialTech.com](http://www.GlacialTech.com)

© 2010 GlacialTech Inc. All rights reserved.