


User Manual

Intel LGA775/1155/1156/1366

AMD FM1, AM2, AM2+, AM3




Inspiring Cooling Technology
www.GlacialTech.com



• Installation


Step 1

The nuts are inserted into the bracket and which can be moved along the path to fit AMD and Intel motherboards.



Step 2


Sponges (9) are used to combine the motherboard and bracket to avoid the bracket is spin off.




Step 3

Remove fan firstly, and then install Intel or AMD clips on the thermal module.

For Intel




For AMD




Step 4

Applying thermal grease (11) on the surface of CPU, and then install thermal module on the CPU and motherboard by screws (8)



Step 5

Integrate the fan and thermal module, and then plug fan connector into the onboard 12V power connector.



GlacialTech®
Enlighten Your Humanity

9F, No. 352, Sec. 2, Zhongshan Rd., Zhonghe Dist., New Taipei City, Taiwan, 235, R.O.C.
TEL: +886 2 2244-1227 FAX: +886 2 2244-1228 E-mail: sales@glacialtech.com

For further information, please consult our website: www.GlacialTech.com

©2011 GlacialTech Inc. All rights reserved. All brand names and trademarks are the properties of their respective owners.

The specifications are subject to change without notice.

Made in China

17-XXXXS000001